




Replace light bulbs as necessary

Replace tie beams as necessary







- 12 New Douglas Fir 16"x16" needle beams
 - eams
- New sawn wood stringers
- New steel rod cross-bracing

- 13 New Douglas Fir 16"x16" floor beams
- 17 New nail-laminated wood deck
- 21 New Douglas Fir bottom chords

- Concrete repairs to bridge abutments
- 23 Bridge deck elevation and approach grades will remain the same
- 24 Height restriction bar to prevent oversized vehicles from using the bridge
- 25 Fire retardant materials applied to various bridge elements


3 tonne posted load limit to be maintained

	✓ Small Cars, SUVs, Horse & Buggies	1 - 3 tonnes
-0-0	✓ X Pick-up Trucks	1.7 – 3.5 tonnes
	× EMS Vehicles	4 - 8 tonnes
	X School Bus/Small Truck	6 - 12 tonnes
66	X Large truck	13+ tonnes

Height Restriction Bar - North Approach



*Details to be finalized with the input of an architect




Replace end diagonals at pier and strengthen end diagonals at abutments

27 New overhead wood lateral bracing

New timber guiderail





Reinstate interior cladding in short sections at each end of the bridge

30